6 FAH-4 H-600 ANNUAL FACILITY CONDITION SURVEY AND ANNUAL INSPECTION SUMMARY REPORT (AIS)

(TL:FCLH-1; 06-16-1997)

6 FAH-4 H-601 ANNUAL FACILITY CONDITION SURVEY PROGRAM

(TL:FCLH-1; 06-16-1997)

- a. The Annual Facility Condition Survey is an annual assessment of facilities conditions by technically qualified maintenance personnel.
 - b. Inspectors look for:
 - Structural deficiencies
 - Electrical deficiencies
 - Mechanical deficiencies
- c. All U.S. Government-owned and long-term leased facilities should be surveyed in detail annually. Where deficiencies exist, complete a facility condition survey deficiency format for each project. A sample completed facility deficiency format is shown in 6 FAH-4 H-601 Exhibit H-601.

6 FAH-4 H-603 FACILITY CONDITION DEFICIENCIES

(TL:FCLH-1; 06-16-1997)

Deficiencies are problems found in the property that require:

- Maintenance
- Repair
- Replacement

6 FAH-4 H-604 ANNUAL INSPECTION SUMMARY (AIS)

(TL:FCLH-1; 06-16-1997)

- a. The AIS is a summary of deficiencies taken from the annual facility condition survey deficiency formats. An example is given as 6 FAH-4 H-604 Exhibit H-604.
 - b. Only maintenance and repair work can be shown on the AIS.
 - c. The AIS acts as a maintenance management tool for:
 - Justifying funds for unfunded facility condition survey deficiencies;
 - Developing long-term facilities maintenance objectives;
 - Developing repair/maintenance work plans; and
 - Documenting the maintenance backlog for the post.
 - d. A/FBO requires the AIS and its inclusion in the budget submission.
- e. The post maintenance supervisor or his or her designated representative completes the AIS.
 - f. Do not report items of less than \$1,000.
- g. Individual small items of less than \$1,000 may be combined to reach the minimum amount if these small items are for the same facility and the same type deficiency. Also, individual, same-type deficiency projects in the same facility may be combined into one project, as long as the total cost exceeds \$1,000.

6 FAH-4 H-605 THROUGH H-699 UNASSIGNED

6 FAH-4 H-601 Exhibit H-601 FACILITY CONDITION SURVEY DEFICIENCY FORMAT

(TL:FCLH-1; 06-16-1997)

BLDG. NO BLDG. NAME			CRAFT REQ'D					
DEFICIENCY LOCATION								
ACTION	IN-HOUSE •	CONTRACT •	ESTIMATED COST:					
WHEN?	THIS FY •	FY						
RECOMME	NDED CORRECTI	VE ACTION:						

6 FAH-4 H-604 Exhibit H-604 ANNUAL INSPECTION SUMMARY (AIS)

(TL:FCLH-1; 06-16-1997)

		POINT OF CONTACT					
POST:	POST: MUSCAT		NAME: JOHN SMITH		TELEPHONE : 967-2-865-213		
ITEM NO.	DEFICIENCY DESCRIPTION/ RECOMMENDED ACTION	FACILITY NO.	FACILITY TITLE	CURRENT COST ESTIMATE	SCOPE	PROJEC T NO.	
001	Repair A/C Plant	015	Chancery	125,000	CS	97-01	
002	Repair Roof	015	Chancery	40,000	3000SF	97-02	
003	Repair Roof	020	Warehouse	25,000	2500SF	97-03	